G-04 Series Replacement Parts Kits

TO ORDER REPLACEMENT PARTS KIT: A Replacement Parts Kit contains 11 digits corresponding to customer-specified design options.

1	Γ	2	ı	2	[4	[Е	[,	7	0		10	[11
'		2		3		4		5		0	'	lo l	9			'

Digit	Order Code	Description							
1-3		Pump Configuration							
	G04	For all G-04 Pumps							
4		Kit Designator							
	K	Complete Fluid End Kit							
	D	Diaphragm Kit							
	V	Valve Kit (diaphragm not included)							
5-6		Pump Head Version							
	51	Pump Head Version							
7		Diaphragm & O-ring Material							
	G	Viton®-XT							
	T	Buna-N-XS							
8		Valve Seat Material							
	D	Tungsten Carbide							
	Н	17-4 PH Stainless Steel							
	N	Nitronic 50							
	T	Hastelloy® C							
-	Х	Not included in Diaphragm Kit							
9		Valve Material							
	D	Tungsten Carbide							
	F	17-4 PH Stainless Steel – Machined							
	N	Nitronic 50							
	T	Hastelloy® C							
	Х	Not included in Diaphragm Kit							
10		Valve Springs							
	E	Elgiloy®							
	S	316 Stainless Steel							
	T	Hastelloy® C							
	Х	Not included in Diaphragm Kit							
11	_	Valve Spring Retainers							
	C	Celcon							
	H	17-7 PH Stainless Steel							
	M P	Kynar®							
	T	Polypropylene Hastelloy® C							
	Y	Nylon							
	X	Not included in Diaphragm Kit							

	Kit Designator					
Part Number*	Description	Qty	K	D	٧	
D03-018	Diaphragm	3	•	•		
D25-073	O-ring, manifold	2	•	•	•	
D25-046	O-ring, valve seat	6	•		•	
D03-020	Valve seat	6	•		•	
D03-021	Valve	6	•		•	
D03-022	Valve spring	6	•		•	
D03-092	Tetra seal**	6	•		•	
D03-023	Retainer, valve spring	6	•		•	
D03-125-1011	Washer, dampening***	6	•		•	
A01-113-3400	Threadlocker	1	•	•		

^{*} Last four digits of part numbers with —____ refer to specific material of construction.



WANNER ENGINEERING, INC.

1204 Chestnut Avenue, Minneapolis, MN 55403 TEL: (612) 332-5681 FAX: (612) 332-6937 TOLL-FREE FAX [US only]: (800) 332-6812

www.hydra-cell.com

email: sales@wannereng.com

^{**} Not included with metal spring retainers.

^{***} Note: dampening washer not used in newer models. The thickness of valve seat is increased on newer models to eliminate the need for the dampening washers.